

## **CAUTION: Winter Road Conditions – Be Prepared!**

Active and passive control of avalanche zones may occur along the Lillooet River FSR and the road can be closed at any time for such control activities, if and when required. Avalanche technicians will block the road on either side of avalanche control area during control activities and once the area is deemed safe, the road will be reopened.

---


### **WINTER 2016-2017**

**The following roads will be kept clear until the third week of December:**

- Lillooet River FSR up to the Upper Lillooet River HEF intake including; parking at KM 42, pullout at KM 48 (Salal Creek FSR Junction), pullout KM 49
- Pebble Mainline Road (aka Camp Road) to allow access to the camp
- Both powerhouse access roads

**NOTE:** As we start to commission the two facilities, we will be reducing how far along the Lillooet River FSR we will be plowing. When this occurs, snowmachine parking areas will be located at the furthest extent of the plowed road with a snowmachine staging area.

---



# Project Update

All work sites are operational - **PLEASE DRIVE WITH CAUTION**

KM	Activity along the Lillooet River FSR
KM 37.5	Check Point Booth is in place 24 hr/day.
KM 38.5	Boulder Creek HEF Tunnel Portal site is open. Boulder Creek HEF Powerhouse/switchyard/tailrace site is open.
KM 39.5	Boulder Intake – <b>Gate closed</b> at KM 3 for Mountain Goats
KM 39.7	Drive cautiously in this area – especially KM 39.7 to Km 41.2 as this is a narrow section of road (one-way traffic at a time). Please note the new traffic control lights in place through this area.
KM 41.2	Upper Lillooet River HEF Powerhouse/switchyard/tailrace site is open.
KM 42	Parking area cleared, trail open but slippery and icy in many sections. <b>USE AT OWN RISK</b>
KM 42-44	Trucks entering Truckwash Creek area.
KM 44	Upper Lillooet River HEF Downstream Tunnel Portal site open.
KM 47-49	Upper Lillooet River HEF Intake and Upstream Tunnel Portal site open with limited activity. Bypass Road at KM48 (change in road alignment) due to November 8-9 flood damage to two crossing structures. Road works taking place around KM 49-KM 49.5.
Road Name	Activities associated with Transmission Line (South side)
Lillooet South FSR	N/A
Salmon Main Road	Post-flood road repairs underway.
Miller Bench FSR	N/A
Miller Creek area	N/A
Pemberton Creek area	Clearing of Hazard Trees.
Rutherford Creek FSR	N/A

### Heavy Equipment leaving site

- Heavy equipment and large trailers are being trucked from site.
- Supply deliveries will be trucked to site on a regular basis.

### General updates on other industrial users

- Road Users continue to complete repairs and maintenance to the FSR between KM0-KM48

For up-to-date forestry road information, please go to:  
<https://www.for.gov.bc.ca/dsq/Engineering/RoadInformation.htm>