



Project Update

Extreme Weather Event has closed Lillooet River FSR

- Lillooet River Forest Service Road is closed at KM 26 due to a debris flow that is covering the road for 35-40 feet.
- Many other sections of the road are covered in water and starting to wash out sections of the road.
- The prime road use permit holder (Squamish Mills) will be on site tomorrow to assess the status of the road. Repairs and maintenance to be determined.
- Date of re-opening unknown